

Color Coding for RJ45 Connections

PIN 1: Orange/Green (Infrared)

PIN 2: Orange (Infrared)

PIN 3: White/Green (5V Ground)

PIN 4: Green (Down)

PIN 5: White/Blue (+5V)

PIN 6: Blue (Up)

PIN 7: White/Brown (+12V)

PIN 8: Brown (12V Ground)

12V Trigger

PIN 7 (+12V)

PIN 8 (12V Ground)

Dry Contacts

PIN 3: 5V Ground

PIN 4: Down

PIN 6: Up

Down: PIN (3+4)

Up: PIN (3+6)

Stop: PIN (3+4+6)

Infrared Sensor

PIN 5: +5V

